

Surface Agent

A wax-containing clear liquid formulation designed for use with either gel coats or resins to reduce air sensitivity and inhibition. The function of Surfacing Agent is to migrate or bloom to the exposed surface of the laminate or casting, it creates a thin film preventing air contact with the resin and allowing cure to take place. When subsequent plies are to be applied, this wax film naturally must be removed by sanding to facilitate interply adhesion. Since various resins and gel coats may react differently, the exact ratio that works best for a particular process is up to the user to determine. Ambient temperature and catalyst ratio may effect outcome. When brushing or rolling material, care should be exercised not to remove film by overlapping strokes excessively since it is necessary for the Surface Agent to form a film.

For use as in a final coat to eliminate surface tackiness 1 to 2% by weight is the normal level, although less may be sufficient with some resins.

For use as a sanding coat, add to Laminating Resin at a ratio of 3 to 5% by weight. 10 ml. to a quart equals approximately 1%.

Brushes, rollers, containers, mixing sticks, etc. must be clean for consistent results. Measure accurately and mix thoroughly. Keep a log of quantities, ratios, ambient temperature, gel time, job size and results, for future repeatability. For industrial use only. Read MSDS before usage.

Store in a cool place in original container not over 75° F.

NET CONTENTS: lbs.

Packaged by: Fiberglass Supply, Inc.
 314 West Depot
 Bingen, WA 98605-0345
 (509) 493-3464

WARNING: This product contains/produces chemicals known to the state of California to cause cancer, and birth defects or other reproductive harm.

D. O. T. Shipping Name:
COATING SOLUTION, 3, UN1139, III, FLAMMABLE LIQUID
CONTAINS: STYRENE MONOMER

EMERGENCY CONTACT NUMBER:

1 (800) 424-9300

CAUTION: FLAMMABLE LIQUID, CLASS 1C

WARNING: CAUSES EYE IRRITATION-HARMFUL IF INHALED-
MAY CAUSE SKIN IRRITATION-HARMFUL IF SWALLOWED-
FLAMMABLE.

Avoid contact with eyes and prolonged or repeated contact with skin. Wear goggles and face shield when handling. Avoid breathing of vapor or spray mist. Use only with adequate ventilation. Keep away from heat, spark, and flame.

FIRST AID: In case of contact with skin, flush with plenty of water. For eyes immediately flush with plenty of water for 15 minutes and CALL A PHYSICIAN. Wash clothes before re-use. If inhaled, remove to fresh air. If not breathing give artificial respiration, preferably mouth to mouth. If breathing is difficult, give oxygen. If swallowed, CALL A PHYSICIAN IMMEDIATELY. DO NOT induce vomiting.

ATTENTION: THIS CONTAINER IS HAZARDOUS WHEN EMPTIED.
Since emptied containers retain product residues (vapor or liquid), all labeled hazard precautions must be observed.

CONSULT MSDS for more complete handling information prior to use.

FOR INDUSTRIAL USE ONLY

HMI S Rating: (**H=2**, **F=3**, **R=1**)

KEEP OUT OF REACH OF CHILDREN