

# Partall # 2

## Green wax

Partall paste No. 2 is a wax based compound containing no silicones. Useful as a general purpose parting agent and as a prime coat to be applied to mold surfaces prior to Partall No. 10 Mold Release Film (PVA).

CAUTION: CONTAINS PETROLEUM DISTILLATES  
KEEP LID TIGHTLY CLOSED WHEN NOT IN USE

Net Contents:                    lbs.

Packaged by:     **Fiberglass Supply, Inc.**  
314 West Depot  
Bingen, WA 98605-0345  
(509) 493-3464

### Directions:

1. Surface should be thoroughly clean prior to application.
2. Apply in small amounts with clean rag.
3. Buff when moderately dry, preferably with Turkish Toweling.
4. For breaking in new molds, apply 3 to 5 coats over a period of time.
5. After break-in, one coat of Partall Paste is adequate for three to five molding cycles.
6. Review Partall No. 10 for instructions for use as a prime coat for PVA.

Read MSDS before usage.

HMI S Rating: ( **H=1**, **F=2**, **R=0** )

**KEEP OUT OF REACH OF CHILDREN**